

Download 1993 Yamaha C115tlrr Outboard Service Repair Maintenance Manual Factory

I have a 1993 115 4 cyl mercury outboard. After a high speed run the other evening I put the throttle back and tried to get the boat to idle. The rpm s would not drop below 1700 rpm. I have checked linkage ,rebuilt fuel pump, removed and cleaned carbs, checked trigger at switch box with ohm meter(ok) and checked compression #1 110 #2 100 #3 110 #4 110.